GIB SEA 422 - 1992

Ref : YVCHA664417



Main datas

Builder :
Year : 1992
Length : 12,30
Draft : 1,70
hull : Monohull
Area : Turkey
Berth details :
Flag : France

Subtype :
Architect : Joubert-nivelt design
Material : GRP
Beam : 3,95
keel : Fixed Keel
Life Raft : Yes
Mooring : No
Leasing in progress : No

Engines

Brand : PERKINS
Montage : In Board (IB)
Power Unit. (CV) : 50
Comments : Very good condition. Maintenance traceability on request.propeller shaft alternator
Shaft : Shaft drive

Brand : PERKINS
Fuel : Diesel
Comments : Very good condition. Maintenance traceability on request.propeller shaft alternator
Tank : 180

Shaft : Shaft drive

© Xboat 2024

Facilities

Sailor Cabin : 0
WC : Sailor
Helm : No
Double Cabin : 3
Head : 2
Flybridge : No

Electronics

Radar details : FURUNO 1720
Sounder details : TRIDATA ST 60
Plotter details :
Watermaker details :
Radar : Yes
Autopilot : Yes
GPS : Yes
VHF : Yes
Watermaker : No

Bridge equipment

Hydrolic Gangway : No
Bath platform : Yes
Winter cover : Yes
Furling mainsail : No
Gangway : Yes
Davits : No
Electric windlass : Yes
Furling genoa : Yes
Teak cockpit : Yes
Teak deck : No

Major equipment

Stern thruster : No
Group and thruster details :
Charger and AC details : Wind turbine WINDBUGGER Aerogen /4 /// 2 solar panels SOLARA /// a battery charger TECPRO 3 ways 25 AMP /// shaft alternator //// engine alternator 20A
Tender : No
Details :
Bow Thruster : No
Marine Gen. : No
AC : No
Flaps : No
Tender Engine : No

© Xboat 2024

Appliances

Freezer : No
Microwaves : No
Oven : Yes
Heating details :
Heater : No
TV : No
TV antenna : No
SAT-TV : No

IceMaker : No
Oven : Yes
Electric stove : No
SAT-TV : No

Divers

Comments : Very nice unit with exceptional maintenance. Boat of character and very reliable. Detailed inventory and Traceability maintenance, equipment & work on request.
Work of AUGUST 2017:

- replacement of the shaft chair
- replacement of the hydraulube ring
- replacement of the Volvo gland

In 2018 All upper works were stripped and refurbished with a preventive treatment anti osmosis + epoxy. (hull, keel, rudder)
Sandblasting and fine sanding, by a specialized company then,

- protective treatment with 2 layers of Gelshields plus
- treatment with epoxy fertilizer
- then 2/3 coats of epoxy primer
- then anti fouling

The first owner of the boat was Michel Malinovsky.

© Xboat 2024

Médias











© Xboat 2024














© Xboat 2024








© Xboat 2024