

## **MARYLAND 37 - 1999**



#### https://www.xboat.uk/1851-FOUNTAINE-PAJOT\_MARYLAND-37.html



### **Main datas**

**Builder : Fountaine Pajot** 

Year: 1999 Length: 11,50 Draft minimum: 1,00 Hull: Catamaran Area: France East Med

Berth details : Flag : France

Subtype: Architect: Material: GRP Beam: 5,10 keel: Fixed Keel Life Raft: Yes

Mooring: No

Leasing in progress: No

## **Engines**

Model:

Montage : In Board (IB) Power Unit. (CV) : 140

Hours: 2750

Fuel capacity: 1500

Brand : Yanmar Fuel : Diesel Engine(s) : 2

Owner's Comments: Engines fully reconditioned

by the official Yanmar agent in 2020.

Drive : Shaft drive

#### **Facilities**

Sailor Cabin: 0 WC: Electric Helm: Yes Double Cabin: 2

Head: 2 Berth: 5

Flybridge: Yes

### **Electronics**

Radar details : Pilot details : Sounder details :

**GPS** details: Automatic Identification System

Plotter details : Converter 12/220 : No Watermaker details : Radar : Yes
Autopilot : Yes
Sounder : Yes
GPS : Yes

**Chartplotter: Yes** 

VHF: Yes

Watermaker: No

## **Bridge equipment**

Hydrolic Gangway: No
Bath platform: Yes
Winter cover: Yes
Sprayhood: No
Teak cockpit: No
Sails details:

Gangway : Yes
Davits : Yes

Electric windlass : Yes Cockpit awning : Yes Furling genoa : No Spinnaker : No

## **Major equipment**

Stern thruster : No

Group and thruster details : Charger and AC details :

Black Water : Yes Tender : No Details : Bow Thruster : No Marine Gen. : No

AC: Yes

Hot water : Yes Flaps : No

**Tender Engine : No** 

### **Appliances**

Freezer: No
Microwaves: No
Electric stove: No
Heating details:
Dishwasher: No

TV: Yes

IceMaker: No
Oven: Yes
Gas stove: Yes
Heater: No

Washing machine : No TV antenna : Yes SAT-TV : No

#### **Owner's Comments**

My Maryland 37 is a sought-after and rare model on the market: Notably in 2019-2020: reconditioning of the 2 engines by the official Yanmar agent. In December 2022, for safety reasons: - the 2 propeller shafts were replaced (one was slightly corroded), - the 2 hydrolube rings were replaced with new ones, - the propellers were rebalanced, - the engine silent-blocks were replaced, During a sea trial with the mechanic, the maximum speed was recorded at 19 knots, with no overheating and no vibrations. For reference, the ideal cruising speed is around 10/12 knots. Antifouling and anode replacement is done every year. It is perfectly equipped for cruising. Solar panels on the Bimini since 2022. I continue to maintain it with the utmost care.

Limitation of liability: XBOAT presents the details of the boat as supplied to us by the owner.

Owners may make errors or changes without notifying us. This information is not contractual and does not bind XBOAT in any way. It cannot be opposed by a visitor or a buyer.

# Médias

























































































