



Main datas

Builder :

Year : 2002

Length : 13,50

Draft : 1,95

hull : Monohull

Area : France Brittany Northern

Berth details :

Flag : France

Subtype :

Architect : Bruce roberts

Material : Steel

Beam : 4,15

keel : Deep keel

Life Raft : No

Mooring : Yes

Leasing in progress : No

Engines

Brand : PERKINS

Montage : In Board (IB)

Power Unit. (CV) : 82

Comments : 2 engines (6 stainless steel tanks)

Shaft : Shaft drive

Brand : PERKINS

Fuel : Diesel

Comments : ENGINE :PERKINS engine reconditioned with 2 engines- model: 4236- diesel- shaft line 50 mm- fuel capacity: 1000 liters (6 stainless steel tanks)

Shaft : Shaft drive

Facilities

Sailor Cabin : 1	Double Cabin : 3
WC : Sailor	Head : 3
Helm : No	Flybridge : No

Electronics

Radar details :	Radar : No
Sounder details :	Autopilot : No
Plotter details :	GPS : No
Watermaker details :	VHF : Yes
	Watermaker : No

Bridge equipment

Hydrolic Gangway : No	Gangway : No
Bath platform : No	Davits : No
Winter cover : No	Electric windlass : Yes
Furling mainsail : Yes	Furling genoa : Yes
Spinnaker : No	Spinnaker : No
Teak cockpit : No	Teak deck : No

Major equipment

Stern thruster : No	Bow Thruster : No
Group and thruster details :	Marine Gen. : No
Charger and AC details :	AC : No
Tender : No	Flaps : No
Details :	Tender Engine : No

Appliances

Freezer : No

Microwaves : No

Oven : Yes

Heating details :

Heater : No

TV : No

TV antenna : No

SAT-TV : No

IceMaker : No

Oven : Yes

Electric stove : No

SAT-TV : No

Divers

Comments : Steel sailboat to renovate (with work!)

- BRUCE ROBERTS 43 MK2

- overall length: 13.50 m

- width: 4.05m

- draft: 1.95 m

- weight about 15/17 tons

- steel shaped shell

- bridge: 3 mm

- shell: 4mm

- keel: 6 mm

- sole: 18mm

SAILS:

- furling mainsail (from 2002)

- furling genoa (from 2002)

- second forestay: storm jib on carabiners

ENGINE :

reconditioned PERKINS engine with 2 engines

- model: 4236

- diesel

- shaft line 50 mm

- fuel capacity: 1000 liters (6 stainless steel tanks)

- Steel sailboat to renovate

- great potential

- necessary repair work

- we do not provide any quotes, the buyer has to come and see on site and make an offer.

- any serious offer to purchase will be carefully studied





















































































