



Main datas

Builder : Fountaine Pajot

Year : 2004

Length : 14,00

Draft minimum : 1,30

Hull : Catamaran

Area : Mayotte

Berth details :

Flag : France

Subtype :

Architect : Joubert & nivelt

Material : GRP

Beam : 7,30

keel : Unknown

Life Raft : Yes

Mooring : No

Leasing in progress : No

Engines

Model : 4JH5E

Montage : In Board (IB)

Power Unit. (CV) : 50

Hours : 1200

Fuel capacity : 450

Brand : YANMAR

Fuel : Diesel

Engine(s) : 2

Owner's Comments : Recent engines large revision 2023,
1200h Babord and 1600 hours starboard, cables,
new control lever.

Great revision 2023
Drive : Saildrive

Facilities

Sailor Cabin : 4

WC : Sailor

Helm : No

Double Cabin : 4

Head : 4

Berth : 10

Flybridge : No

Electronics

Radar details :

Pilot details : Raymarine 2024

Sounder details : Raymarine 2024

GPS details : Raymarine 2025

Plotter details :

Converter 12/220 : Yes

Watermaker details : Sneaker 40/60L/H 2024

Radar : No

Autopilot : Yes

Sounder : Yes

GPS : Yes

Chartplotter : Yes

VHF : Yes

Watermaker : Yes

Bridge equipment

Hydraulic Gangway : No

Bath platform : No

Winter cover : No

Sprayhood : No

Furling mainsail : No

Spinnaker : Yes

Gangway : No

Davits : Yes

Electric windlass : Yes

Cockpit awning : Yes

Teak deck : No

Spinnaker : Yes

Major equipment

Stern thruster : No

Group and thruster details :

Charger and AC details :

Black Water : Yes

Tender : Yes

Details :

Bow Thruster : No

Marine Gen. : No

AC : No

Hot water : Yes

Flaps : No

Tender Engine : Yes

Appliances

Freezer : No

Microwaves : No

Electric stove : No

Heating details :

Dishwasher : No

TV : No

IceMaker : No

Oven : No

Gas stove : Yes

Heater : No

Washing machine : No

TV antenna : No

SAT-TV : No

Owner's Comments

The owner tells us:

"The unit presented is one of the last Bahia 46 out of the Fontaine Pajot sites.

Specially prepared and neat for one of the site directors, this Bahia 46 was bought by the current owner in 2009.

This boat comes out of a complete refit site in 2024 in a site.

The following works were carried out, int / ext and polish paintings, reinforcements of fins and safrans, replacement of safrans levels, preventive epoxy treatment osmosis, replacement of 6 valves in prevention?.

Lots of money was invested in this very complete refit. "

Limitation of liability : XBOAT presents the details of the boat as supplied to us by the owner.

Owners may make errors or changes without notifying us. This information is not contractual and does not bind XBOAT in any way. It cannot be opposed by a visitor or a buyer.













