



PRINCESS 56 FLY - 1997

Ref : YVCHA665194



Main datas

Shipyard :PRINCESS YACHTS
Architect :Marine Projects
Year :1997
Made of :GRP
Length :17.15 m
Width :4.62 m
Draft :1.14 m
Hull :Monohull

Liferaft :Yes
Area :Portugal
Berth place available :Yes
Berth place details :â,- 6000 / y
Office :Denia

Remaining leasing :No
Flag :BELGIUM
type of boat :Pleasure

Engines

Brand :VOLVO
Engine model :TAMD 122P EDC
Fuel type :Diesel
Mounting :In Board (IB)
Number of engines :2
Power unit (hp) :610
Engines details :Engines se

Hours :770
Transmission :Shaft drive
Fuel tank :2140

Facilities

Number of double cabins : 3
Number of single cabins :0
Number of crew cabins : 1
Number of bathroom :2

Type of WC :Electric
Number of berths :8
Wheelhouse :Yes
Flybridge :Yes

Electronics

Radar :Yes
Radar details :
Autopilot :Yes
Autopilot details :
12/220 converter :Yes
Depth sounder :Yes
Sounder details :

GPS: Yes
Plotter :Yes
Plotter details :
VHF: Yes
Watermaker :No
Watermaker specs :

Bridge equipment

Gangway :Yes
Hydraulic :Yes
Davits :Yes
Aft platform :Yes
Electrical windlass :Yes

Teak deck :Yes

Winter cover :Yes
Teak cockpit :No
Cockpit cover :Yes

Major equipment

Bow thruster :Yes
Marine generator :Yes
Marine generator details :12 KW, 810
Air conditioning :Yes
Charger or air conditioning details :
Hot water :Yes

Holding tank :Yes
Tender :Yes
Tender Outboard :Yes
Tender and ob details :JET AVON 80 HP
jet out
Stern thruster :No
Flaps :Yes

Appliances

Ice maker :Yes
Fridge :2
Freezer :Yes
Oven :Yes
Microwave :Yes
Gas stove :No
Electrical stove :No
Heating :Yes
Heating details :Reversible

Laundry :Yes
Dishwasher :No
TV antenna :Yes
TV :Yes
Sat tv antenna :Yes

Miscellaneous

Comments :The photos are a year old, except those of the flybridge and the engines which are recent.

Boat sold as is.

Annual engine overhaul not done in 2021, therefore, to be done.

Antifouling to do and anodes to change.

All the valves and all the through-hulls are to be changed.

Plan to sand the teak and redo the seals.

Leak repair at a window in the living room.

Repair aft winch.

The sausage of the AVON dinghy must be reattached and the gel coat applied with polish.

Provide generator and air conditioning service.

Provide a new hot water tank.

The boat can also be sold totally overhauled for a higher price.





