

https://www.xboat.uk/6098-FOUNTAINE-PAJOT_BAHIA-46.html



Main datas

Builder : Fountaine Pajot

Year: 2004
Length: 14,00
Draft minimum: 1,30
Hull: Catamaran
Area: Mayotte
Berth details:
Flag: France

Subtype:

Architect: Joubert & nivelt

Material : GRP Beam : 7,30 keel : Unknown Life Raft : Yes Mooring : No

Leasing in progress: No

Engines

Model: 4JH5E

Montage : In Board (IB) Power Unit. (CV) : 50

Hours: 1400 Fuel capacity: 450 Brand : YANMAR Fuel : Diesel Engine(s) : 2

Owner's Comments: Recent engines, major

overhaul 2023,

1200h port and 1600h starboard bases, cables, control lever new.

Major overhaul 2023 Drive : Saildrive

Facilities

Sailor Cabin : 4 WC : Sailor Helm : No Double Cabin: 4

Head: 4
Berth: 10
Flybridge: No

Electronics

Radar details:

Pilot details : RAYMARINE 2024 Sounder details : RAYMARINE 2024 GPS details : RAYMARINE 2025

Plotter details:

Converter 12/220: Yes

Watermaker details: SNEKER 40/60L/H 2024

Radar : No Autopilot : Yes

Sounder : Yes GPS : Yes

Chartplotter: Yes

VHF: Yes

Watermaker: Yes

Bridge equipment

Hydrolic Gangway : No Bath platform : No

Winter cover : No Sprayhood : No Teak cockpit : No

Gangway : No Davits : Yes

Electric windlass : Yes Cockpit awning : Yes Furling genoa : Yes

Spinnaker: Yes

Major equipment

Stern thruster: No

Group and thruster details : Charger and AC details :

Black Water : Yes Tender : Yes Details : Bow Thruster : No Marine Gen. : No

AC: No

Hot water : Yes Flaps : No

Tender Engine: Yes

Appliances

Freezer: No
Microwaves: No
Electric stove: No
Heating details:
Dishwasher: No

TV: No

IceMaker: No
Oven: No
Gas stove: Yes
Heater: No

Washing machine : No

TV antenna : No SAT-TV : No

Owner's Comments

The owner informs us: "My Bahia 46 presented is one of the last Bahia 46s to come out of the Fountaine Pajot shipyards. Specially prepared and cared for for one of the directors of the Shipyard, this Bahia 46 was purchased by the current owner in 2009. This boat comes out of a complete refit in 2024 at a shipyard. The following work has been carried out: interior/exterior painting and polishing, reinforcement of the fins and rudders, replacement of the rudder bearings, preventive epoxy osmosis treatment, replacement of 6 valves as a precaution ... A lot of money has been invested in this very complete refit."

Limitation of liability: XBOAT presents the details of the boat as supplied to us by the owner.

Owners may make errors or changes without notifying us. This information is not contractual and does not bind XBOAT in any way. It cannot be opposed by a visitor or a buyer.

Médias













