



SBPEM S 570 - 12000 euros - 1995

Ref : NYMAH561085



Main datas

Shipyard :SBPEM
Architect :
Year :1995
Made of :GRP Poly
Length :5.70 m
Width :2.48 m
Draft :0.60 m
Headroom :0.00
Hull :Monohull
Weight in tons :0.00
Navigation category :

Liferaft :No
Liferaft year model :
Area :France Brittany
Berth place available :No
Berth place details :
Office :Lorient
Price :12 000
Remaining leasing :No
Remaining amount vat paid :0
Flag :FRENCH

Engines

Brand :YAMAHA
Engine model :50CV/4TPS
Fuel type :Gas/petrol
Mounting :HB (OB)
Number of engines :1
Power unit (hp) :50
Engines details :

Hours :0
Transmission :Outboarder
Propellers :
Fuel tank :25
Cruising speed :
Max speed :0

Facilities

Number of double cabins: 0
Number of single cabins :0
Number of crew cabins : 0
Number of bathroom :0

Type of WC :
Number of berths :0
Wheelhouse :Yes
Flybridge :No

Electronics

Radar :No
Radar details :
Autopilot :No
Autopilot details :
12/220 converter :No
Loch: No
Depth sounder :No
Sounder details :
GPS: No

Plotter :No
Plotter details :
Navtex: No
BLU: No
VHF: No
Watermaker :No
Watermaker specs :

Bridge equipment

Gangway :No
Hydraulic :No
Davits :No
Aft platform :No
Bathroom ladder :Yes
Electrical windlass :No
Manual windlass :No
Sun mattress :No
Windshield cover :No
Winter cover :No
Teak cockpit :No
Cockpit cover :No
Wood interior :No

Teak deck :No

Major equipment

Bow thruster :No
Extinguisher :No
Marine generator :No
Marine generator details :
Number of batteries :1
Air conditioning :No
Shore power :No
Number of chargers :0
Charger or air conditioning details :
Hot water :No

Holding tank :No
Water tank capacity :0
Anchorage :1
Tender :No
Tender Outboard :No
Tender and ob details :
Stern thruster :No
Wiper :Yes
Flaps :No

Appliances

Ice maker :No
Fridge :0
Freezer :No
Stove :No
Oven :No
Microwave :No
Gas stove :No
Electrical stove :No
Heating :No
Heating details :

Laundry :No
Dishwasher :No
TV antenna :No
TV :No
Radio tape :No
Cd radio :No
Outdoor speakers :No
DVD :No
Sat tv antenna :No

Decoration

Inside upholstery :
Outside upholstery :

Wood interior :No

Miscellaneous

Hardware :No
Curative osmosis treatment :No
Curative osmosis treatment :curatif :
Comments :

Preventive osmosis treatment :No
Curative osmosis treatment :preventif :
Cockpit glass door :No



