



Main datas

Builder : Fountaine Pajot

Year : 1999

Length : 11,50

Draft minimum : 1,00

Hull : Catamaran

Area : France East Med

Berth details :

Flag : France

Subtype :

Architect :

Material : GRP

Beam : 5,10

keel : Fixed Keel

Life Raft : Yes

Mooring : No

Leasing in progress : No

Engines

Model :

Montage : In Board (IB)

Power Unit. (CV) : 140

Hours : 2750

Fuel capacity : 1500

Brand : Yanmar

Fuel : Diesel

Engine(s) : 2

Owner's Comments : Engines fully reconditioned by the official Yanmar agent in 2020.

Drive : Shaft drive

Facilities

Sailor Cabin : 0

WC : Electric

Helm : Yes

Double Cabin : 2

Head : 2

Berth : 5

Flybridge : Yes

Electronics

Radar details :

Pilot details :

Sounder details :

GPS details : Automatic Identification System

Plotter details :

Converter 12/220 : No

Watermaker details :

Radar : Yes

Autopilot : Yes

Sounder : Yes

GPS : Yes

Chartplotter : Yes

VHF : Yes

Watermaker : No

Bridge equipment

Hydraulic Gangway : No

Bath platform : Yes

Winter cover : Yes

Sprayhood : No

Teak cockpit : No

Sails details :

Gangway : Yes

Davits : Yes

Electric windlass : Yes

Cockpit awning : Yes

Teak deck : No

Spinnaker : No

Major equipment

Stern thruster : No

Group and thruster details :

Charger and AC details :

Black Water : Yes

Tender : No

Details :

Bow Thruster : No

Marine Gen. : No

AC : Yes

Hot water : Yes

Flaps : No

Tender Engine : No

Appliances

Freezer : No

Microwaves : No

Electric stove : No

Heating details :

Dishwasher : No

TV : Yes

IceMaker : No

Oven : Yes

Gas stove : Yes

Heater : No

Washing machine : No

TV antenna : Yes

SAT-TV : No

Owner's Comments

My Maryland 37 is a sought-after and rare model on the market: Notably in 2019-2020: reconditioning of the 2 engines by the official Yanmar agent. In December 2022, for safety reasons: - the 2 propeller shafts were replaced (one was slightly corroded), - the 2 hydrolube rings were replaced with new ones, - the propellers were rebalanced, - the engine silent-blocks were replaced, During a sea trial with the mechanic, the maximum speed was recorded at 19 knots, with no overheating and no vibrations. For reference, the ideal cruising speed is around 10/12 knots. Antifouling and anode replacement is done every year. It is perfectly equipped for cruising. Solar panels on the Bimini since 2022. I continue to maintain it with the utmost care.

Limitation of liability : XBOAT presents the details of the boat as supplied to us by the owner.

Owners may make errors or changes without notifying us. This information is not contractual and does not bind XBOAT in any way. It cannot be opposed by a visitor or a buyer.

Médias









