

Ref : CHHAM61960



Main datas

Builder : Archambault**Year :** 2007**Length :** 10,59**Draft :** 2,10**hull :** Monohull**Area :** Mayotte**Berth details :****Flag :** France**Subtype :****Architect :****Material :** GRP**Beam :** 3,55**keel :** Fixed Keel**Life Raft :** Yes**Mooring :** No**Leasing in progress :** No

Engines

Brand : YANMAR**Montage :** In Board (IB)**Power Unit. (CV) :** 21**Comments :** Engine revised in 2022**Shaft :** Z drive**Brand :** YANMAR**Fuel :** Diesel**Comments :** Engine revised in 2022**Shaft :** Z drive**Tank :** 0

Facilities

Sailor Cabin : 0	Double Cabin : 2
WC : Sailor	Head : 1
Helm : No	Flybridge : No

Electronics

Radar details :	Radar : No
Sounder details :	Autopilot : Yes
Plotter details :	GPS : Yes
Watermaker details :	VHF : Yes
	Watermaker : No

Bridge equipment

Hydrolic Gangway : No	Gangway : No
Bath platform : No	Davits : No
Winter cover : No	Electric windlass : No
Furling mainsail : No	Furling genoa : No
Roller reefing : No	Spinnaker : Yes
Teak cockpit : No	Teak deck : No

Major equipment

Stern thruster : No	Bow Thruster : No
Group and thruster details :	Marine Gen. : No
Charger and AC details :	AC : No
Tender : No	Flaps : No
Details :	Tender Engine : No

Appliances

Freezer : No

Microwaves : No

Oven : No

Heating details :

Heater : No

TV : No

TV antenna : No

SAT-TV : No

IceMaker : No

Oven : No

Electric stove : No

SAT-TV : No

Divers

Comments : ARCHAMBAULT A35, cruise racing sailboat.

Holder of the Mauritius tour of 2016/2017...

Carbon mast and pole.

Ready to race and cruise fast.

No. of sails

Osmosis curative treatment 2022

Rudder bearings

In offshore navigation, the boat has proven to be safe and comfortable at sea. Its interior layout and equipment, WC, Shower, Hot water tank, Fridge, Two-burner kitchen... add the interest of comfort sufficient for this fast unit which brings a lot of pleasure and satisfaction.

Carbon mat

Carbon pole

Original rod standing rigging

1 hollow tufluf type prop

tiller version

1 saffron

Curative osmosis treatment in progress

Dry boat visible in Mauritius

Rudder bearing under renovation

Plan for revision of the Harken mainsail linchpin rail





