



Main datas

Builder : Beneteau

Year : 1991

Length : 8,10

Draft minimum : 0,55

Hull : Monohull

Area : France Med

Berth details : lease until 12/31/2022 - ?8,000, then permanent tenant

Flag : France

Subtype :

Architect :

Material : GRP

Beam : 2,95

keel : Unknown

Life Raft : No

Mooring : Yes

Leasing in progress : No

Engines

Model : TAM41

Montage : In Board (IB)

Power Unit. (CV) : 200

Hours : 2150

Fuel capacity : 150

Brand : VOLVO

Fuel : Diesel

Engine(s) : 1

Owner's Comments : tamd 41. revision 2021 with cable gland.Exhaust elbow + turbo new 2021

Drive : Shaft drive

Facilities

Sailor Cabin : 0

WC : Sailor

Helm : Yes

Double Cabin : 1

Head : 1

Berth : 4

Flybridge : No

Electronics

Radar details : RAYTHEON R10

Pilot details : AUTOHELM 4000

Sounder details :

GPS details : GARMIN GPS MAP 720S

Plotter details :

Converter 12/220 : No

Watermaker details :

Radar : Yes

Autopilot : Yes

Sounder : Yes

GPS : Yes

Chartplotter : Yes

VHF : Yes

Watermaker : No

Bridge equipment

Hydrolic Gangway : No

Bath platform : Yes

Winter cover : No

Sprayhood : No

Teak cockpit : No

Sails details :

Gangway : No

Davits : No

Electric windlass : Yes

Cockpit awning : No

Teak deck : No

Spinnaker : No

Major equipment

Stern thruster : No

Group and thruster details : prop bow 2019: 5500 euros

Charger and AC details :

Black Water : No

Tender : No

Details :

Bow Thruster : Yes

Marine Gen. : No

AC : No

Hot water : No

Flaps : No

Tender Engine : No

Appliances

Freezer : No

Microwaves : No

Electric stove : No

Heating details :

Dishwasher : No

TV : Yes

IceMaker : No

Oven : No

Gas stove : Yes

Heater : No

Washing machine : No

TV antenna : No

SAT-TV : Yes

Owner's Comments

Offshore fishing or comfortable cruising, the Antares 805 skillfully handles both roles. The double cabin optimizes both speed and sea comfort, as well as safety and course stability. New exhaust elbow and turbo in 2021. Bow thruster installed in 2019 for ?5,500. Aft deck and swim platform installed in 2019 for ?800. Refrigerator replaced in 2019 for ?1,000. TV installed in 2019 for ?200. Stem packing renewed in 2019. Engine serviced in 2019.

Limitation of liability : XBOAT presents the details of the boat as supplied to us by the owner.

Owners may make errors or changes without notifying us. This information is not contractual and does not bind XBOAT in any way. It cannot be opposed by a visitor or a buyer.





