



# GUY COUACH 1501 FLY - 1991

Ref : ALCRE66948



## Main datas

Shipyard :GUY COUACH  
Architect :  
Year :1991  
Made of :GRP  
Length :15.00 m  
Width :4.29 m  
Draft :1.50 m  
Hull :Monohull

Liferaft :Yes  
Area :Spain Catalonia  
Berth place available :Yes  
Berth place details :in spain  
Office :Barcelona

Remaining leasing :No  
Flag :Poland  
type of boat :Pleasure

## Engines

Brand :GM  
Engine model :Detroit Diesel  
Fuel type :Diesel  
Mounting :In Board (IB)  
Number of engines :2  
Power unit (hp) :475  
Engines details :New engine

Hours :1800  
Transmission :Shaft drive  
Fuel tank :2000

## Facilities

Number of double cabins : 3  
Number of single cabins :0  
Number of crew cabins : 1  
Number of bathroom :2

Type of WC :Sailor  
Number of berths :6  
Wheelhouse :Yes  
Flybridge :Yes

## Electronics

Radar :Yes  
Radar details :FURUNO  
Autopilot :Yes  
Autopilot details :RAYMARINE  
12/220 converter :Yes  
Depth sounder :Yes  
Sounder details :

GPS: Yes  
Plotter :Yes  
Plotter details :  
VHF: Yes  
Watermaker :No  
Watermaker specs :

---

## Bridge equipment

Gangway :Yes  
Hydraulic :Yes  
Davits :No  
Aft platform :Yes  
Electrical windlass :Yes

Teak deck :Yes

Winter cover :Yes  
Teak cockpit :Yes  
Cockpit cover :Yes

---

## Major equipment

Bow thruster :Yes  
Marine generator :Yes  
Marine generator details :Onan MDKAV  
Air conditioning :Yes  
Charger or air conditioning details :Condaria  
Hot water :Yes

Holding tank :Yes  
Tender :Yes  
Tender Outboard :Yes  
Tender and ob details :Zodiac  
Stern thruster :No  
Flaps :Yes

---

## Appliances

Ice maker :No  
Fridge :2  
Freezer :Yes  
Oven :Yes  
Microwave :Yes  
Gas stove :No  
Electrical stove :Yes  
Heating :No  
Heating details :

Laundry :No  
Dishwasher :No  
TV antenna :Yes  
TV :Yes  
Sat tv antenna :No

## Miscellaneous

Comments :Repairs July 2015: Complete Sigma Ecofleet antifouling, special treatment for shafts, propellers, rudders in Velox patent, new anodes.

- Repairs June 2016: new Mastervolt battery charger and new hydraulic gangway piston.

- Complete refit of the teak deck in June 2016 with recalling and complete sanding of the deck.

- Repairs May 2017: Complete antifouling and special treatment for new shafts / propellers / rudders, anodes and bushings. It was also polished to hull and very comfortable boat to anchor, fish and live in it. Large solarium with mattresses with towel covers in the bow. Complete teak bathtub, cushions and towel covers for all mats, Bimini flybridge and bathtub.

2021 important renovation works, bills available.





